

# CI-5000 SERIES



CI-5010A



CI-5200A



CI-5500A

## FEATURES

- > Tare setting with ten key
- > RS-232C Interface
- > Peak-Hold function, RFI/EMI screened
- > Watch-Dog circuitry (System restoration)
- > Weight Back-up (Saving of weight at sudden power failure)
- > Various specification of weight conversion speed
- > External input: zero, start, stop, tare/printer
- > External output: zero, high & low limit, completion  
(CI-5200A/5500A)
- > PC Command Mode support
- > Single-pass automatic span calibration
- > RFI/EMI screened
- > Automatic zero tracking

## APPLICATION

- > Measuring instrument tester, Platform scale, Truck scale

## OPTIONS

- > RS-442/485 interface
- > Analog Output/BCD Output