

CI-8000V *SERIES*



— *FEATURES*

- > Ideal function for Checker, Hopper, Packer
- > Watch-Dog circuitry (System restoration)
- > Weight Back-up
(Saving of weight at sudden power failure)
- > Functions for discharge weighing, accumulation weighing, continuity accumulation weighing
- > Set-up and set-up value display by 100 set point
- > Built-in 10 inside relays (3-step control)

— *APPLICATION*

- > Measuring instrument tester, Checker, Hopper, Packer

— *OPTIONS*

- > RS-442/485 interface
- > Analog Output/BCD Output